



TECHNICAL DATASHEET

REFERENCE : **E2121**

Old référence :

ALUMINIZED COAT

Description :

made of carbon fleece / para-aramid 430g / m². - Cowhide leather collar - Walking gaiters - Underarm ventilation - 50mm wide flame-retardant self-gripping side fastening and / or snap fasteners - KEVLAR® wire seams. is available in unlined or lined version in proban® treated cotton Variations: collapsible collar, slit and / or wrist strap, inner pocket, reinforcements on the most exposed parts, super insulated interlayer, special custom sizes, quick-loop closure, back ventilation, ...

Dimensions :

Sizes available S M L XL XXL XXL

body and arm protection against thermal risks (flames, convective and radiant heat, projection of molten metal)



Recommandation

The materials of this article do not contain any substance that can harm the health of the user

This PPE is in conformity with the requirements of the Directive 89/686/CEE.
EPI de catégorie 3, (AET) N°033/2015/1175CENTEXBEL

The CE marking on these items means the respect for the essentials requirements of European Directive on PPE based on the standard ISO 13688



A1 B1 C4 D3 E3 F1

ISO 11612

- A Limited flame spread
- B Convective Heat (1 à 3)
- C Radiant Heat (1 à 4)
- D Projection of molten aluminium (1 à 3)
- E Projection of molten iron (1 à 3)
- F Contact Heat (1 à 3)

Use only within the risks covered above



Maintenance :

A dirty clothe may cause a reduced protection/
no washing recommended, clean with a damp sponge

Storage : Protected from the light and in a dry place, free of moisture, oils, greases...

Recommandation :

to ensure optimal protection, this equipment must be worn closed and supplemented with appropriate PPE (gaiters, gloves, head protection) and work clothes.

Lenght	Coat/Apron		Sizes	B et C
	A			
120 cm	164-170 cm		S – T2	92-96 cm
130 cm	170-182 cm		M – T3	96-104 cm
140 cm	182-188 cm		L – T4	104-112 cm
150 cm	188-194 cm		XL – T5	112-120 cm
160 cm	194-200 cm		XXL – T6	120-128 cm

For coveralls, take the greatest size between B or C. The measures must be taken on the person wearing his work clothes, because this equipment is worn over. In doubt between two sizes choose the larger one.

